SERVICE BULLETIN

ATTN: SERVICE MANAGER

GAME: Secret Service Pinball

DATE:

#013

September 9, 1988

SUBJECT: Preventative Maintenance

for the Flipper End of

Stroke Switch

SYMPTOM:

The long blade of the end of stroke switch (EOS Sw.) breaks where

it comes out of the body of the switch.

PROBLEM:

The GOS Sw. actuator screw is too long. This results in excessive

flexing of the long blade which causes it to eventually snap near

the switch body.

SOLUTION:

Remove and replace the EOS Sw. actuator screw and cap with those

enclosed.

Pete Gustafson

Field Service Manager

Page 1 of 1