




Nº 136A SERVICE BULLETIN



Joe Blackwell
Director, Parts Sales &
Technical Support

Susan White
Parts Sales
Manager

Patty Schraps
Parts Stockroom
Manager

Chas Siddiqi
Technical Support
Engineer

Jay Alfer
Technical Support Doc.
Administrator

TO: Parts & Service Managers

DATE: June 21, 2002

SUBJ: **PLAYBOY U7 Sound ROM Update DOES NOT RESOLVE the problem**

Reference: Service Bulletin 136, Dated May 2, 2002, Subject: Early Production **PLAYBOY U7 Sound ROM Change**

Notice!

We have received several calls from operators who have installed the U7 Sound ROM update.

This ROM change did not **completely** resolve the problem. When this **U7 ROM** problem is **completely corrected**, we will release another new version of **U7 Sound code**.

Please wait until further notice when an update is available. For now, please disregard **Service Bulletin 136** which was posted on our website and faxed to all distributors.

We apologize for any inconvenience which may have occurred.

Please phone or eMail with any questions or comments at the below numbers or address.

• 2020 Janice Ave • Melrose Park, IL 60160 • Tel 708-345-7700 (Option 1) • Toll-Free (USA/Canada) 1-800-542-5377 • Fax 708-345-7889 •

Received via Fax? For a better copy, download from our website: www.sternpinball.com/bulletins.htm

S.B. Nº 136A
Page 1 of 1

Want Service Bulletins by eMail? Request by eMail: parts.service@sternpinball.com